



**DESIGN & CONSTRUCTION GROUP  
THE GOVERNOR NELSON A. ROCKEFELLER  
EMPIRE STATE PLAZA  
ALBANY, NY 12242**

---

**ADDENDUM NO. 1 TO PROJECT NO. 46162**

**CONSTRUCTION WORK  
PROVIDE MASONRY REPAIR & REPOINTING  
STATE ARMORY  
25 KIERSTED AVENUE  
KINGSTON, NEW YORK**

June 21, 2022

**NOTE:** This Addendum forms a part of the Contract Documents. Insert it in the Project Manual. Acknowledge receipt of this Addendum in the space provided on the Bid Form.

**INTRODUCTORY INFORMATION**

1. DOCUMENT 000115 LIST OF DRAWINGS: Discard the Document bound in the Project Manual and substitute the accompanying Document (page 000115-1) noted "Printed 06/21/2022".

**BIDDING REQUIREMENTS**

2. DOCUMENT 003126 EXISTING HAZARDOUS MATERIAL INFORMATION: Discard the Document bound in the Project Manual and substitute the accompanying Document (page 003126-1) noted "Printed 06/21/2022".

**END OF ADDENDUM**

Erik T. Deyoe, P.E.  
Director, Division of Design  
Design & Construction

## **LIST OF DRAWINGS**

### **1.01 DRAWINGS**

- A. The Contract Drawings, which accompany this Project Manual and form a part of the Contract Documents, are listed on the Title Sheet of the Drawings.

**END OF LIST**

## **DOCUMENT 003126**

### **EXISTING HAZARDOUS MATERIAL INFORMATION**

#### **1.01 ASBESTOS SURVEY REPORT**

Samples listed in the report were collected at the Project Site and tested for Asbestos Containing Materials (ACM). The report was compiled for New York State Office of General Services, Design and Construction Group by an ELAP certified laboratory. In order to determine the Asbestos content, samples were analyzed by polarized light microscopy (PLM) and/or transmission electron microscopy (TEM). The report is intended for the State design and estimate purposes only, and is included to provide bidders with that same information available to the State. The Bulk Samples are representative of Homogeneous Area (HA) and is defined as a suspect material of similar age, appearance, function and texture. All field information was organized in accordance with 40 CFR Part 763, Asbestos Hazard Emergency Response Act (AHERA). See the Hazardous Material Survey Report, Pre-Renovation, Asbestos, Lead and Polychlorinated Biphenyls (PCB) dated January 28, 2020, included in the Appendix, for type, condition, location and approximate quantity of ACM.

#### **1.02 LEAD SURVEY REPORT**

Samples listed in the report were collected at the Project Site and tested for Lead content. The report was compiled for New York State Office of General Services, Design and Construction Group by an ELAP certified laboratory. In order to determine the lead content the Atomic Absorption method or a XRF Analyzer was used. This report is intended for State design and estimate purposes only, and is included to provide bidders with the same information available to the State. The samples are representative of like materials in the Work area. All lead containing materials may not have been sampled. See the Hazardous Material Survey Report, Pre-Renovation, Asbestos, Lead and Polychlorinated Biphenyls (PCB) dated January 28, 2020, included in the Appendix, for details.

#### **1.03 PCB SAMPLING REPORT**

Samples listed in the report were collected at the Project Site and tested for PCBs. The report was compiled for New York State Office of General Services, Design and Construction Group by an ELAP certified laboratory. Bulk, wipe or air sampling was used in determining the PCB content. This report is intended for State design and estimate purposes only, and is included to provide bidders with the same information available to the State. All PCB containing materials may not have been sampled. See the Hazardous Material Survey Report, Pre-Renovation, Asbestos, Lead and Polychlorinated Biphenyls (PCB) dated January 28, 2020, included in the Appendix, for details.

**END OF DOCUMENT**