



STATE OF NEW YORK
OFFICE OF GENERAL SERVICES
DESIGN AND CONSTRUCTION GROUP
THE GOVERNOR NELSON A. ROCKEFELLER
EMPIRE STATE PLAZA
ALBANY, NY 12242



ADDENDUM NO. 1 TO PROJECT NO. 44237

CONSTRUCTION WORK

**REPLACE WINDOWS AND SIDING SYSTEM, BUILDING NOS. 1, 2 AND 3
PARKER TRAINING ACADEMY
531 TURKEY HILL ROAD
REDHOOK, NY 12571**

October 24, 2013

NOTE: This Addendum forms a part of the Contract Documents. Insert it in the Project Manual. Acknowledge receipt of this Addendum in the space provided on the Bid Form.

SPECIFICATION GROUP

1. Page 007306 – SUPPLEMENTARY CONDITIONS – WARRANTY EXTENSION, delete page from specification. Not required for this project.

CONSTRUCTION WORK DRAWINGS

2. Drawing No. A-202:
 - a. General Notes: Change note 2 to read “At Building No. 2” instead of “At Building No. 3”
3. Drawing Nos. A-201, A-202 and A-203:
 - a. For the quantity of window units, refer to Building Elevation Drawings A-201, A-202 and A-203 instead of Window Schedule # of units. See Drawing A-501.

END OF ADDENDUM

James Dirolf, P.E.
Director of Design

