



STATE OF NEW YORK
OFFICE OF GENERAL SERVICES
DESIGN AND CONSTRUCTION GROUP
THE GOVERNOR NELSON A. ROCKEFELLER
EMPIRE STATE PLAZA
ALBANY, NY 12242



ADDENDUM NO. 2 TO PROJECT NO. 44596

HVAC WORK and ELECTRICAL WORK

**REPLACE HEATING SYSTEM, VEHICLE BAYS
FLEET MAINTENANCE SHOP
DOT REGION 3, ONONDAGA COUNTY
5430 SOUTH BAY ROAD
NORTH SYRACUSE, NY 13212**

August 8, 2013

NOTE: This Addendum forms a part of the Contract Documents. Insert it in the Project Manual.
Acknowledge receipt of this Addendum in the space provided on the Bid Form.

BID QUESTIONS:

1. In furtherance of Response #2 to Bidder's Question #2 - "The boilers are from 1966 and there is a layer of insulation under the jacket. Has it been tested?":

A field visit was conducted on Wednesday, August 7, 2013 to obtain samples for testing of the boiler insulation for presence of asbestos containing materials (ACM's).

It was observed at that time that the boiler insulation is fiberglass and therefore does not contain ACM, and does not need to be tested.

END OF ADDENDUM

James Dirolf, P.E.
Director of Design