



**DESIGN AND CONSTRUCTION GROUP
THE GOVERNOR NELSON A. ROCKEFELLER
EMPIRE STATE PLAZA
ALBANY, NY 12242**

ADDENDUM NO. 2 TO PROJECT NO. 44925

**CONSTRUCTION WORK, HVAC WORK, PLUMBING WORK, AND ELECTRICAL WORK
REHABILITATE SHOWERS, ANNEX BUILDINGS 32-38
FRANKLIN CORRECTIONAL FACILITY
62 BARE HILL ROAD
MALONE, NY**

September 15, 2015

NOTE: This Addendum forms a part of the Contract Documents. Insert it in the Project Manual.
Acknowledge receipt of this Addendum in the space provided on the Bid Form.

CONSTRUCTION WORK DRAWINGS

1. Drawing No. A-102, CONSTRUCTION KEYED NOTE 10:
 - a. Change to read “Existing ceiling system (fiberglass reinforced panels over (2) layers of gypsum board suspended from roof deck) to be removed in its entirety. Refer to drawing H-101 for the extent of removals required to be completed as mold remediation.”

END OF ADDENDUM

Margaret F. Larkin
Executive Director
Design and Construction